
CORRES. CONTRO	DL.		
OUTGOING LTR. N	0		
DOE ORDER # 4700.1			
05-RF-002	14		
	LTR	ENC	
DIETER, T.J.	_	, -	
FERRERA, D.W.	X		
LINDSAY, D.C.	-		KAISER*HILL
LONG, J.	~+	_	
LYLE, J.L.			COMPANY
MARTINEZ, L. A.	- 1	_	
PIZZUTO, V.M.	-1	 :	
SHELTON, D.C.	-	;	
SPEARS, M.S.	-1		
TUOR, N. R.			
TOOK, N. K.	-1	 .	
	-	<u> </u>	
BEAN, C.	\dashv		March 1, 2005 05-RF-00214
DECK, C:	\dashv		
FOSS, D.	\dashv	_	
FRANCIS, M.	$\overline{\mathbf{v}}$		
FREIBOTH, C.	4	<u> </u>	
GEIS, A.	Ÿ	:	
GIBBS, F.	X	إ	Gary Morgan, Functional Lead
HUMISTON, T.	_		Cadre Project Management Division
KNAPP, S.	Ш		DOE, RFPO
LAVORATO, K.	Ш		DOL, KITO
LINSINBIGLER, H.	IJ	<u></u>	
MYERS, K.	Ş	Ş.	TRANSMITTAL OF CLOSE OUT REPORT FOR BUILDING 906 FEG-002-05
NESTA, S.	X	<u> </u>	
NORTH, K.			
OMAN, K.			Attached is the Closeout Report for the Type 1 facility Building 906 – Waste Storage Facility.
PLAPPERT, R.	<u> </u>		Please note that a copy of the report has been submitted to the CERCLA AR by the Kaiser-Hill
PRIMROSE, A.	Щ	_	
RICHARDELLA, R.		<u> </u>	RISS project.
SNYDER, D.P.	_	L	
SWARTZ, J.M.			Please contact Steve Nesta x6386 with questions or concerns.
WARD, D.A.		_	The second secon
WIEMELT, K.		i.	
SILLS, S.	ļ	<u> </u>	Fuls-All
SHULER, K.	_	<u> </u>	The -1 ft
	<u> </u>	—	Frank E. Gibbs
	L_	L	
	_	<u> </u>	Deputy Project Manager
	_	<u> </u>	Remediation, Industrial D&D, and Site Services
	 	 	
CORRES.CONTROL	ΙX		Attachment
ADMIN RECRD/T130G	Ľ	X	Attachment:
TRAFFIC	Ŀ	<u> </u>	As Stated
PATS/130		<u> </u>	
CLASSIFICATIO	N:		SMN:pvt
UCNI	┡	 	Olivity. Par
UNCLASSIFIED	!	<u> </u>	
CONFIDENTIAL	↓_	Щ.	Orig. and 1 cc – Gary Morgan
SECRET	_	<u> </u>	
AUTHORIZED CLASSIFI			
SIGNATURE: TIME		4-	CC:
(J FaGJapH			Joseph Legare
Date: 03/01/05			Deanna McCranie
IN REPLY TO RFP CC N	0.:	_	
ACTION ITEM STA	<i>-</i>		necelly in
ACTION LEEM STA	1115	· ·	





ADMIN RECORD

ARTIAL/OPEN

ORIG. & TYPIST INITIALS: SMN:pvt

RF-46469(Rev.9/94)

Facility No.
Building 906
Facility Descriptor:
B906 - Waste Storage facility
Project:
RISS
Date of Demolition:
Additional Information:
(Must include information on environmental releases and conditions of site at turnover to Environmental Restoration)

Section B. Final Characterization Data
Reconnaissance Level Characterization Report
(concurrence received)

In-process Characterization
Pre-Demolition Survey Report (approval received)

Post-Demolition Survey Report (as necessary)

Reconnaissance Level Characterization Report (RLCR) for
Building 906 – Concurrence from Steven Gunderson to Joe
Legare on January 31, 2005

N/A

RLC functioned as PDS

N/A

Post-Demolition Survey Report (as neces	sary) IN/A			
Section C. Waste Data (complete cat	agorios as annronriato)			
· -	egories us upproprime)			
Sanitary Disposal	BFI Foothills Landfill, Golden CO			
Disposal Site:				
Waste Volume (yd³):	3380			
Waste Weight (tons):	1615.22			
Additional Information:	Building debris			
Hazardous Disposal				
Disposal Site:	Kettleman Hills Facility, Kettleman City, CA or Bethlehem Apparatus			
Disposar Site.	Co, Hellertown, PA			
Waste Volume (yd³):	Minor Amounts			
Additional Information:	Electronic circuit boards, thermostats, exit signs, batteries, fluorescent			
Additional information.	light bulbs and any other RCRA hazardous components were removed			
·	and taken to the RFCA temporary unit for combination with like waste			
	streams for proper disposal.			
	Situatio for proper disposar.			
TSCA Waste Disposal				
Disposal Site:	BFI Tower Rd. Landfill, Commerce City, CO			
Waste Volume (m ³):	Minor Amounts			
Additional Information:	PCB ballasts were removed and taken to the RFCA temporary unit for			
	combination with like waste streams for proper disposal.			
Ashartan Wagta Dignagal				
Asbestos Waste Disposal	N/A			
Disposal Site:	N/A			
Waste Volume (m ³):	N/A			
Additional Information:	A CONTRACTOR OF THE CONTRACTOR			
Low-Level Waste Disposal	•			
Disposal Site:	N/A			
Waste Volume (m ³):	N/A			
Additional Information:				
Low-Level Mixed Waste Disposal	NT/A			
Disposal Site:	N/A			
Waste Volume (m ³):	N/A			
Additional Information:	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE			
Recycled Material				
Recycle Facility:	N/A			
Waste Volume (m ³):	N/A			
Additional Information:				
Property Disposition				
Receiver Locations (major items only):	N/A			
Volume (m ³):				
I and the second				

Weight (tons):	·			
Additional Information:				
Section D. Approvals		T-/		
Kaiser-Hill Project Manager	CJ FREJAOTI	James	07	2/28/05
	Name/Signature	10		Date


Additional Facility Information

Building 906 was an approximately 25,000 square foot building constructed in 1994. The structure was a steel frame building built on a concrete foundation. The walls and roof were constructed of insulated aluminum attached to a steel frame.

Building 906 had the following utilities: electrical and fire protection provided by an overhead sprinkler system and wall mounted fire extinguishers.

Building 906 contained RCRA Container Storage Unit MS 001, Sub-Unit 14, which was closed in accordance with the Closure Description Document, submitted December 27, 2004. CDPHE acceptance of the administrative closure was received on January 24, 2005.

The entire B906 structure was removed during D&D activities, and sent offsite for disposal. The utilities were disconnected and removed to at least three feet below final grade as indicated on the attached map. There are no remaining structural components, utility lines, or parts of the foundation. The buildings are not in an IHSS or PAC and no staining was observed after the slab was removed; therefore no soil sampling is required.



L